Versions and History

Wired comunication modules

TELETEK

TTE GPRS Standard

Current Version	Date	Version	Changes
→→→	14.11.2022	HW.6.51/SW.9.55	FW Change: 1. Canceling SMS User and SMS Backup when roaming card onboard 2. Adding 10 new events for Commelit devices 3. Event name "TR" -> changed to "TH" 4. Server times as in 4G 5. Added more initialization timeouts
	29.1.2021	HW6.5/SW9.5.4	SW: Eclipse 8+ support
	18.6.2020	HW6.5/SW9.5.3	SW: Bugfix related to the roaming card support
	27.3.2020	HW6.5/SW9.5.2	SW: Redirect Command, Rouming card support, no time stamp is expected when working with SIA09
	14.11.2019	HW6.5/SW9.5.1	SW: Events generated by the module itself(such as Power up), will be send through the account number of the Eclipse panel.
	26.8.2019	HW6.5/SW9.5.0	HW: Component changed - Micro SIM card holder will be used from now on, replacing the previous Mini SIM holder.
	2.7.2019	HW6.3.2/SW9.5.0	SW: NULL event period is programmable
	4.4.2019	HW6.3.2/SW9.4.2	SIA09
	31.1.2018	HW6.3.2/SW9.4.0	SW: 1. Voice dialer function added - report and management 2. Improved stabillity 3. Connection with Eclipse 99 is now supported 4. Abillity to send group of events(up to 16 events) 5. Firmware update is improved
	27.10.2017	HW6.3.2/SW9.3.2	Terminals(input/output) changed
	31.1.2017	HW6.3/SW9.3.2	1.Firmware update via ProsTE 2.Message sending during open sesion 3.Removed bug when switching to January 1
	11.7.2016	HW6.3/SW9.3.0	Communication improvements in case of low RSSI signal
	-	SW 9.3.0	Improvements: - DNS support - SMS support for both - backup server and user - SMS output control - Ajax Standard support

TTE GPRS Simple

Current Version	Date	Version	Changes
→→→	29.1.2021	HW6.5/SW9.5.4	SW: Eclipse 8+ support
	18.6.2020	HW6.5/SW9.5.3	SW: Bugfix related to the roaming card support
	27.3.2020	HW6.5/SW9.5.2	SW: Redirect Command, Roaming card support, no time stamp is expected when working with SIA09
	14.11.2019	HW6.5/SW9.5.1	SW: Events generated by the module itself(such as Power up), will be send through the account number of the Eclipse panel.
	26.8.2019	HW6.5/SW9.5.0	HW: Component changed - Micro SIM card holder will be used from now on, replacing the previous Mini SIM holder.
	2.7.2019	HW6.3.3/SW9.5.0	SW: NULL event period is programmable
	4.4.2019	HW6.3.3/SW9.4.2	SIA09
	27.3.2018	HW6.3.3/SW9.41	Stability improvements in regard to the HW changes (removed components)
	22.3.2018	HW6.3.3/SW9.3.2	HW changes - removed components for stability
	27.10.2017	HW6.3.2/SW9.3.2	Terminals changed
	31.1.2017	HW6.3/SW9.3.2	1.Firmware update via ProsTE 2.Message sending during open sesion 3.Removed bug when switching to January 1
	11.7.2016	HW6.3/SW9.3.0	Communication improvements in case of low RSSI signal
	-	SW 9.3.0	Improvements: - DNS support - SMS support for both - backup server and user - SMS output control - Ajax Standard support

Last Update 20.12.2022